


- The setting of zero and sensitivity adjustment is by potentiometers.
- 14 bits accuracy.



### Power supply


It has two Inputs:

1. 18-24 VDC
2. Depending on version:
  - 48VAC
  - 115VAC
  - 230VAC

### Analog outputs

- 0-10V (Optional 0-5V)
- 4-20mA (Optional 0-20mA)

### Load cell connection



Dimensions in mm.

